| Ref | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|-----|-------|---|---------------------------------|---------------------|---------|------------------|
| L1 | 4021 | (second two pair double couple) near4 (torque near3 (element portion part member structure)) | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 11:54 |
| L2 | 1861 | ((second two pair double couple) near4 (torque near3 (element portion part member structure))).clm. | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 11:55 |
| L3 | 74 | 1 and ((second two pair double plurality couple) near3 load).clm. | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 11:55 |
| L4 | 45 | 2 and ((second two pair double plurality couple) near3 load).clm. | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 13:44 |
| L5 | 1 | 3 and (stress near4 (measur\$5 sens\$5 detect\$5 indicat\$5 monitor\$5 calculat\$5)). clm. | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 11:58 |
| L6 | 0 | 4 and (stress near4 (measur\$5 sens\$5 detect\$5 indicat\$5 monitor\$5 calculat\$5)). clm. | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 11:58 |
| L7 | 1 | 3 and (stress near4 (measur\$5 sens\$5 detect\$5 indicat\$5 monitor\$5 calculat\$5)) | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 13:42 |
| L8 | 0 | 4 and (stress near4 (measur\$5 sens\$5 detect\$5 indicat\$5 monitor\$5 calculat\$5)) | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 11:58 |
| L9 | 2 | 4 and ((stress strain) near6 (measur\$5 sens\$5 detect\$5 indicat\$5 monitor\$5 calculat\$5)) | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 11:59 |
| L10 | 10645 | 73/862\$5.cels. | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 13:43 |
| L11 | 72 | 10 and 2 | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 14:31 |
| L12 | 1 | 11 and ((second two pair double plurality couple) near3 load).clm. | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 13:45 |
| L13 | 7 | 11 and ((second two pair double plurality couple) near3 load) | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 13:45 |
| L14 | 32 | 11 and load | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 13:52 |
| L15 | 16 | 11 and (load and stress) | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 13:52 |
| L16 | 332 | 73/862.333.ccls. | US-PGPUB; USPAT; EPO; JPO | OR | OFF | 2005/01/31 14:31 |